

Inspection Body Accreditation Programme

Schedule to

CERTIFICATE OF ACCREDITATION



Chemsafety Ltd

Client Number 9360

PO Box 8141, Riccarton, Christchurch, 8440
2B, 303 Blenheim Road, Upper Riccarton, Christchurch, 8041

Telephone 03 366-3700

www.chemsafety.co.nz

Authorised Representative

Mrs Livia Fioravanti
Laboratory Manager

Programme

Inspection Body

Accreditation Number 154

Initial Accreditation Date 13 August 2019

Conformance Standard

ISO/IEC 17020:2012

Conformity assessment — Requirements for the operation of various types of bodies performing inspection

Inspection Services Summary

Asbestos Surveying and Sampling Inspection

Operations Manager
Authorisation:

Issue 3

Date: 16/03/21

Page 1 of 2



Chemsafety Ltd
Inspection Body

Accreditation Number 154

SCOPE OF ACCREDITATION

Asbestos Surveying and Sampling Inspection

Independence Type Type A Inspection Body

Inspection Type Product (materials and documentation)

Inspection Fields Occupational Hygiene
 ○ Asbestos Containing Materials (ACMs)


Inspection Type Surveying and Sampling for Asbestos

Range of Inspection

- Identification of potential Asbestos Containing Materials (ACMs)
 - Management Surveys
 - Domestic
 - Commercial
 - Industrial
 - Refurbishment and Demolition Surveys
 - Domestic
 - Commercial
 - Industrial
- Sampling for Verification of Asbestos
- Evaluation of survey results (including the provision of advice about the management of risks and priority assessment)
- Re-inspection of identified or suspected Asbestos Containing Materials (ACMs) in surveyed premises

Inspection Requirements/Criteria

New Zealand Health and Safety at Work (Asbestos) Regulations 2016
 WorkSafe New Zealand Good Practice Guidelines - Conducting Asbestos Surveys
 WorkSafe New Zealand Approved Code of Practice - Management and Removal of Asbestos

Operations Manager Authorisation:		Issue 3	Date: 16/03/21	Page 2 of 2
--------------------------------------	---	---------	----------------	-------------